

Photos of Sugar Island North Shore and Lake George Channel 2009 to 2011

Chippewa County Health Department
Environmental Health Division
508 Ashmun St. Suite 120
Sault Ste Marie, MI 49783

Contacts:

Christine Daley, Lead Sanitarian
Shane Albrecht, Lead Technician

The next 8 photos were taken on the
North Shore of Sugar Island
2009 to 2011













DATE
CONTENTS:

7-12-11

Sugar Island
Twp Park

6/27/11
Found at Sugar Is
Twp Park



DATE
6/18/11

7/18/11
N. Channel





FLOATING DEBRIS - NORTH CHANNEL - ST. MARY'S RIVER

SUGAR ISLAND PARK BEACH

NORTH CHANNEL

BETWEEN CESTP RELEASE PIPE AND AIR DALE FLYING SERVICE (E. COLI COUNT 636)

6/27/11

7/12/11

7/18/11

7/18/11





SUGAR ISLAND PARK BEACH

6/27/11

7/12/11



FLOATING DEBRIS - NORTH CHANNEL - ST. MARY'S RIVER

NORTH CHANNEL

BETWEEN EESTP RELEASE PIPE AND AIR-DALE FLYING SERVICE (E.C)

7/18/11

7/18/11




CHANNEL ST. MARY'S RIVER

E PIPE AND AIR-DALE FLYING SERVICE (E.COLI COUNT 636)

7/18/11



Plume of debris found in the Lake George Channel July 18, 2011



2007-2010 Routine Monitoring Locations

Note: These locations were not monitored during the 2011 season.

